

Veberod Gem Gallery

Bangles III – Fidget Bracelet

This class will further your exposure to soldering bigger pieces and moving metal. Skills include soldering, annealing, stamping, forging and [mostly likely] repairing mistakes!

Prerequisite: Silversmithing III

Please plan to provide all your own consumables. You will be able to purchase anything you need at Veberod Gem Gallery during class. Being able to see clearly is essential to your success, so bring any portable lighting and magnification you are accustomed to using (cheaters, OptiVisor, Telesight).



Supplies Required

20ga Sterling Silver sheet, 1” x 9”
1x4 Sterling Silver wire
Hard Silver Solder
Boric Acid Flux
Batterns Flux
Flux bottle
Saw Blades

Tools used (tools marked with an *asterisk are regularly stocked in the student benches)

*Jeweler’s saw
*Solder Cutting Pliers
*Solder Pick
Torch
*Soldering Surface
*Soldering Tweezers
*Insulated Cross-lock tweezers
*Third Hand
*Chain Nose Pliers
Mitre Cutting Jig
Decorative/Alphabet Stamps
Chasing Hammer
Round Bracelet Mandrel
Goldsmithing Hammer
Non-Marring Cross-Peen hammer
Flat Nose Pliers (or 2 Chain Nose)
*Flush Cutters
Files
Magnification
3M Polishing Paper

Notes on tools/supplies

This list is designed to help you determine what to bring from home. Please **DO NOT** buy anything before class if you don’t already have it. Many times there are factors that will determine your best choice and we will discuss all this at class. Bring what you have, and don’t stress about what you don’t.

We prefer not to offer kits for our classes. We try to encourage students to pick equipment and supplies (stones, beads etc.) based on their individual creativity. Often there are several options available and you may have some items already.

Please **mark** tools from home so they are identifiable as your own. If you have any questions regarding the cost of tools, supplies or anything else about the class, please contact us at 952.595.8338.