

# Veberod Gem Gallery

## Tube Riveted Metal Beads

These wonderful beads are assembled using only connected techniques, and they are a fun blend of color, metal, shape and texture. Learn to cut discs out of sheet, dome discs, tube rivet and more.

Prerequisites- Silversmithing 3, Cold Connections I

### Supplies Required

Silver, Copper or Brass Sheet – 20ga  
Tubing  
Pattern material for rolling mill (optional)

**Tools used** (tools marked with an \*asterisk are regularly stocked in the student benches)

- \*Jeweler's saw
- Saw blades
- Files
- \*Disc Cutters
- \*Dapping/Doming block with punches
- \*Brass Hammer
- \*Domed Head Chasing Hammer
- \*Chasing Hammer
- Setting burs
- \*Bur Lube
- Miter Cutting Vise
- \*Texture Hammers
- \*Bench Block/Anvil
- \*Center Punch
- \*Ring Clamp
- 3M Polishing Papers
- 400 grit silicon/carbide sandpaper
- Magnification
- \*Ott Light



### Notes on tools/supplies

This list is designed to help you determine what to bring from home. Not everything is required, and we **STRONGLY** recommend not buying anything before class if you don't already have it. Many times there are factors that will determine your best choice and we will discuss all this at class. Bring what you have, and don't stress about what you don't.

We prefer not to offer kits for our classes. We try to encourage students to pick equipment and supplies (stones, beads etc.) based on their individual creativity. Often there are several options available and you may have some items already.

Please **mark** tools from home so they are identifiable as your own. If you have any questions regarding the cost of tools, supplies or anything else about the class, please contact us at 952.595.8338.