

# Veberod Gem Gallery

## Woven and Riveted Cuff

This stunning cuff is a real statement piece that you can make entirely with cold connections. We will be weaving metal to form the cuff and riveting the edges on to create a finished piece. Options available include mixing metals and patterning/texturing metals.

Please plan to provide all your own consumables. You will be able to purchase anything you need at Veberod Gem Gallery during class (except tape). Being able to see clearly is essential to your success, so bring any portable lighting and magnification you are accustomed to using (cheaters, OptiVisor, Telesight).

Prerequisite: Cold Connections I



### Supplies Required

Silver, Copper or Brass wire 16ga  
Silver, Copper or Brass sheet 26 ga 6"x2"  
Silver or Copper sheet 28 ga 6"x3"

### Tools used

Metal Shears  
Files  
Design stamps –or-  
Rolling Mill pattern  
Chasing Hammer or Brass Hammer  
\*\*Masking/Painter's Tape\*\*  
Parallel action nylon jaw pliers  
Duck Billed Pliers  
Scribe  
#55 Drill bit  
Center Punch  
Extra Fine tip permanent marker  
3M Polishing papers  
Flexshaft polishing attachments  
Magnification  
Portable Ott Light

### Notes on tools/supplies

This list is designed to help you determine what to bring from home. Not everything is required, and we **STRONGLY** recommend not buying anything before class if you don't already have it. Many times there are factors that will determine your best choice and we will discuss all this at class. Bring what you have, and don't stress about what you don't.

We prefer not to offer kits for our classes. We try to encourage students to pick equipment and supplies (stones, beads etc.) based on their individual creativity. Often there are several options available and you may have some items already.

Please **mark** tools from home so they are identifiable as your own. If you have any questions regarding the cost of tools, supplies or anything else about the class, please contact us at 952.595.8338.